

Standard Signage for Treatment & Chemical Dosing Plants

OVERHEAD CRANE (Typically used at chlorine drum stores)

OVERHEAD CRANE ISOLATION SIGN (DS WCSS102)



This **Hazard Danger** sign is in landscape format with the standard danger symbol as per AS1319. The other text is black on a white background.
Material - Metal 300 (W) x 225 (H) with the other dimensions as indicated.

- The **Overhead Crane Isolation** sign should be posted on the wall at eye level next to the platform ladder.
- The **Overhead Crane Isolation** sign shall be visible to personnel on normal direction of approach to the platform ladder.